



SPANSION LLC
915 DeGuigne Drive, P.O. Box 3453
Sunnyvale, California 94088-3453, USA

April 10, 2008

Obsolescence Notification No: 2685 Rev.B

Subject: Obsolescence of the CellularRAM Type 3, 64M and 128M pSRAM Multi-Chip Packages (MCPs) products listed below

This is revision B to ACN 2685A originally distributed on January 7, 2008. It is being revised to include additional part numbers that were inadvertently left off. These parts are in bold font under Product Identification.

Spansion LLC is announcing the obsolescence CellularRAM type 3, 64M and 128M pSRAM, and all valid combinations of the Multi-Chip Packages (MCPs) products listed below:

Product Identification:

| | | |
|---------------------------|---------------------------|--------------------------|
| S71WS128NC0BFWA70 | S71WS128NC0BFWA70* | S71WS128NC0BFWAM0 |
| S71WS128NC0BFWAM0F | S71WS128NC0BFWAP0 | S71WS128PC0HF3TR0 |
| S71WS256PC0HF3TL0 | S71WS256PC0HF3TR0 | S71WS256PD0HF3TL0 |
| S71WS256PD0HF3TR0 | S71WS256PD0HF3TR0* | S98WS512PD0FW0060 |
| S98WS512PD0FW0060# | S98WS512PD0FW0060B | |

Product Line: WSD - Wireless Solutions Division

Description of Obsolescence: Obsolescence of MCP Ordering Part Numbers (OPNs), built with 64M and 128M pSRAM, CellularRAM Type 3.

Reason for Obsolescence: These products are being removed from Spansion's portfolio due to commercial die used in the MCPs being end-of-life by the commercial die supplier as a preventive action.

Application Impact: Consolidation of product offerings.

Obsolescence No. 2685B
04/11/08



Replacement Parts:

S71WS128PC0HF3SL0 Replacing S71WS128PC0HF3TL0
S71WS128PC0HF3SR0 Replacing S71WS128PC0HF3TR0
S71WS128PC0HF3SV0 Replacing S71WS128PC0HF3TV0
S71WS256PC0HF3SL0 Replacing S71WS256PC0HF3TL0
S71WS256PC0HF3SR0 Replacing S71WS256PC0HF3TR0
S71WS256PC0HF3SV0 Replacing S71WS256PC0HF3TV0
S71WS256PD0HF3SL0 Replacing S71WS256PD0HF3TL0
S71WS256PD0HF3SR0 Replacing S71WS256PD0HF3TR0
S71WS256PD0HF3SV0 Replacing S71WS256PD0HF3TV0
S98WS512PD0FW0040 Replacing S98WS512PD0FW0060
S98WS128PC0HW0020 Replacing S98WS128PC0FW0010
S98WS256PC0FW003 Replacing S98WS256PC0FW001
S71WS128NC0BAWAN / S71WS128NC0BAWAM Replacing S71WS128NC0BFWAE
S71WS128NC0BAWAP / S71WS128NC0BAWAM Replacing S71WS128NC0BFWAF

Last Order Date: June 30, 2008

Last Shipment Date: December 31, 2008

Products Affected By This Obsolescence (part numbers):

| | |
|--------------------|--------------------|
| S71WS128NC0BFWA70 | S71WS128NC0BFWA70* |
| S71WS128NC0BFWAM0 | S71WS128NC0BFWAM0F |
| S71WS128NC0BFWAP0 | S71WS128PC0HF3TR0 |
| S71WS256PC0HF3TL0 | S71WS256PC0HF3TR0 |
| S71WS256PD0HF3TL0 | S71WS256PD0HF3TR0 |
| S71WS256PD0HF3TR0* | S98WS512PD0FW0060 |
| S98WS512PD0FW0060# | S98WS512PD0FW0060B |

Even though the above date projections are based on the most current product development status information at the time this Obsolescence was issued, they are subject to change. For the latest schedule and any other information, please contact your local sales office or your local distributor.